

ARB1188 / ANB433 / BXH1333

To Suit VS-VY Ecotec Motors

Attention Fitter

JAS has noted a return on these units due to rectifier damage caused by high resistance in vehicle Alternator to Battery wiring.

Please check voltage at rear of Alternator and again at Battery with load and ensure that there is no significant difference in voltage against vehicle specs.

Alternators returned with burnt rectifier links may not be warrantable.

