

Warning on an oil contamination issue SNJ553, SNJ095, SNJ095GQ, SNJ082, SNJ082GQ and SNJ124GQ

JAS have had the 3 different starters above returned with engine oil and diesel ingress issues.

SNJ095, SNJ082 and SNJ124GQ are affected by engine oil that commonly gets into the starters from leaking rocker cover gaskets or leaking rear main seals which then throw the oil into the starter off the flywheel.

SNJ553 damage is caused by a liquid damaging the starter but this time it is diesel from either a leaking diesel pump or leaking fuel system above the starter which causes degradation of the brushes and commutator even faster than engine oil contamination.

This is not a warrantable fault as it is caused by a vehicle issue.

