

ANJ106

Attention Fitter

Our warranty department has advised that some of these units are failing prematurely due to oil contamination.

Please check Vehicle for any oil leaks from Engine and/or Power Steering Pump as even a minor leak can damage unit.

This is not a Manufacturing Defect and therefore NOT Warrantable.

