

Important Information regarding Holden Engines SNB010

Attention Fitter

Please Note Broken Starter Housing Is Not Covered By Your Warranty.



Under normal operating conditions, a starter is not capable of developing enough torque to cause this type of damage.

The problem is typically caused by an engine backfire or “kickback”. GM has released Tech Service Bulletins addressing this issue; the cause is usually one of the following:

- Fuel Pressure Regulator
- Timing Belt
- Misaligned / improperly mounted starter
- Distributer cap
- Valve adjustment
- Use of starting fluid

Any aftermarket GAS system fitted to the vehicle will also need to be checked that it is correctly tuned to Engine.

The correct repair to the engine management system should be made prior to replacement of the starter.

