


## 0 124 525 561, ANB252, ANV068GQ Fitted to BMW 116I 118I 120I Engines N42,N45,N46



JAS have had a number of returned 0 124 525 561 and ANB252 Returned with Oil Damage.

Please advise Customers purchasing this Alternator to identify the source of any oil leaks and repair them to stop potential future contamination of a new Alternator.

Slip Ring and Brush damage results from this contamination, ultimately creating a copper paste from the slip rings as they wear and shorting out the Voltage regulator.

**Engine Oil Damage in the Alternator is not a warrantable fault.**