

TX VALVES

Block - TX Valves

A22-8966



Suits:
Lexus RX350 GSU
Toyota Prius NHW11R, NHW20R

Liquid Inlet: #6
Liquid Outlet: #8

Suction Inlet: #10
Suction Outlet: #10

Tonnage: 1.5



A22-8967



Suits:
John Deere 300 Series
Scania G, P, R, T Series

Liquid Inlet: #6
Liquid Outlet: #8

Suction Inlet: #12
Suction Outlet: #10

Tonnage: 1.5



A22-8968



Suits:
International Eagle
ISX, Signature

Liquid Inlet: #6
Liquid Outlet: #8

Suction Inlet: #8
Suction Outlet: #10

Tonnage: 1.5

2 x Switch Ports



A22-9015GQ



Suits:
Caterpillar 400 Series
Mercedes Benz Sprinter 903, 904
Vito 638

Liquid Inlet: #6 FIOR
Liquid Outlet: #8 FIOR

Suction Inlet: #8 FIOR
Suction Outlet: #10 FIOR

Tonnage: 1.5
S/Heat: 2.8°



A22-9016



Suits:
Mitsubishi Triton ML

Liquid Inlet: #6
Liquid Outlet: #10

Suction Inlet: #10
Suction Outlet: #10

Tonnage: 1.5



A22-9017



Suits:
Audi Q7 Quattro 4L
Porsche Cayenne 9PA
Volkswagen Amarok 2H,
Toureg 7P, 7L

Liquid Inlet: #8
Liquid Outlet: #8

Suction Inlet: #12
Suction Outlet: #10

Tonnage: 2



A22-9018



Suits:
Hyundai i40 VF, ix35 LM
Hyundai Sonata LF
Sportage SI, SL

Liquid Inlet: #6
Liquid Outlet: #8

Suction Inlet: #8
Suction Outlet: #10

Tonnage: 1.5



A22-9019



Suits:
Hyundai i20 PB

Liquid Inlet: #5
Liquid Outlet: #10

Suction Inlet: #10
Suction Outlet: #10

Tonnage: 1.5



A22-9926



Suits:
Hino 300
Mazda CX-5 KE

Liquid Inlet: #6
Liquid Outlet: #10

Suction Inlet: #12
Suction Outlet: #12

Tonnage: 1.5



A22-9927



Suits:
Kenworth K Series, Signature
T Series

Liquid Inlet: #6
Liquid Outlet: #10

Suction Inlet: #10
Suction Outlet: #10

Tonnage: 1.5

Alternative: A22-9927GQ

