

ANJ110

To Suit Mitsubishi 6G72/6G74

Attention Fitter

JAS Oceania has noted a high rate of return on these units due to oil ingress. Please check the original unit for failure due to this problem.

Premature failure of the replacement unit due to oil ingress is not a Manufacturing Defect and will not be covered by Manufactures Warranty.

