

Warranty issues regarding
on fitment ANJ110GQ / ANJ071GQ / ANJ072GQ
Model: Mitsubishi 6G72/6G74

Attention Fitter

Our Warranty Department has noted a high rate of return on these units due to oil ingress. Please check the original unit for failure due to this problem.

Premature failure of the replacement unit due to oil ingress is not a Manufacturing Defect and will not be covered by Manufactures Warranty.

