

TX VALVES

A22-8602GQ



Suits:
Jeep Cherokee KJ, XJ

Liquid Inlet: #6 FIOR
Liquid Outlet: #8 FIOR

Suction Inlet: #10 FIOR
Suction Outlet: #10 FIOR

Tonnage: 1.5
S/Heat: 4.4°

Side Mount Holes



A22-8603



Suits:
**Nissan Pathfinder R50, Patrol Y61
Subaru Impreza GD, GG**

Liquid Inlet: #8
Liquid Outlet: #8

Suction Inlet: #10
Suction Outlet: #10

Tonnage: 1



A22-8604



Suits:
Kia Magnetis MG

Liquid Inlet: #5
Liquid Outlet: #10

Suction Inlet: #10
Suction Outlet: #10

Tonnage: 1.5
S/Heat: 5.3°



A22-8605



Suits:
**BMW 3, 5 Series
Commodore VR, VS
Toyota Lexcen T4, T5**

Liquid Inlet: #6
Liquid Outlet: #8

Suction Inlet: #10
Suction Outlet: #12

Tonnage: 2
S/Heat: 3°



A22-8606



Suits:
**Ford Falcon EBII - EL
Fairlane NC, NF**

Liquid Inlet: #6
Liquid Outlet: #8

Suction Inlet: #10
Suction Outlet: #10

Tonnage: 2.5
S/Heat: 2.8°

P/Switch Port



A22-8606GQ



Suits:
**Ford Falcon EBII - EL
Fairlane NC, NF**

Liquid Inlet: #6
Liquid Outlet: #8

Suction Inlet: #10
Suction Outlet: #10

Tonnage: 2.5
S/Heat: 2.8°

P/Switch Port



A22-8608GQ



Suits:
**Mercedes W123
Peugeot 205**

Liquid Inlet: #6 FIOR
Liquid Outlet: #8 FIOR

Suction Inlet: #8 FIOR
Suction Outlet: #10 FIOR

Tonnage: 2
S/Heat: 2.8°



A22-8610



Suits:
**Freightliner FL80
Kysor Rooftop AC Units**

Liquid Inlet: #6 FIOR
Liquid Outlet: #8 FIOR

Suction Inlet: #8 FIOR
Suction Outlet: #10 FIOR

Tonnage: 1.5
S/Heat: 5°

Alternative: A22-8610GQ



A22-8610GQ



Suits:
**Freightliner FL81
Kysor Rooftop AC Units**

Liquid Inlet: #6 FIOR
Liquid Outlet: #8 FIOR

Suction Inlet: #8 FIOR
Suction Outlet: #10 FIOR

Tonnage: 1.5
S/Heat: 5°

Alternative: A22-8610



A22-8611



Suits:
**BMW 3 Series
Mercedes Benz W126
Volvo Construction FL7**

Liquid Inlet: #6
Liquid Outlet: #8

Suction Inlet: #10
Suction Outlet: #10

Tonnage: 2
S/Heat: 3.5°

