



JAS Product Advice Starters Held in Mesh

Attention Fitter,

The Starter Motor in this packaging is one that has been identified to be commonly held in mesh by a faulty ignition switch or barrel and key assembly.

Please identify the cause of original starter failure and rectify before fitting this new starter.

Starters that have been held in mesh will not be warranted as this is not caused by a manufacturing defect in the starter.

